

```
#####  
#           Archer BE700 System Log  
# Time = 2026-09-11 10:43:30  
# H-Ver = 1.0.0 ; S-Ver = 1.3.1 Build 20260519 rel.14520  
# LAN: I = 192.168.0.1 ; M = 255.255.255.0 ; MAC = 68:7F:F0:16:9A:D7  
# WAN: W = pppoeshare ; I = 0.0.0.0 ; M = 0.0.0.0 ; MAC = 7A:F4:E5:3F:42:6C  
#   G = 0.0.0.0 ; D1 = 0.0.0.0 ; D2 = 0.0.0.0  
# Clients connected: 11 ; WI-FI : 7  
#####  
2026-09-11 10:30:22 ppp[29886]: <6> 261101 ppp receive IPV6CP ACK  
2026-09-11 10:30:22 ppp[29886]: <6> 261091 ppp receive IPCP ACK  
2026-09-11 10:30:22 ppp[29886]: <6> 261100 ppp send IPV6CP Req  
options(ifaceid=cde8:c5f0:a11:acf2 ;)  
2026-09-11 10:30:22 ppp[29886]: <6> 261090 ppp send IPCP Req  
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)  
2026-09-11 10:30:22 ppp[29886]: <6> 261093 ppp receive IPCP NAK  
options(dns1=119.40.106.35;dns2=119.40.106.36;)  
2026-09-11 10:30:22 ppp[29886]: <6> 261100 ppp send IPV6CP Req  
options(ifaceid=ddc3:6c4a:7951:7bce ;)  
2026-09-11 10:30:22 nat[1467]: <6> 211501 Initialization succeeded  
2026-09-11 10:30:22 nat[1467]: <6> 211501 Initialization succeeded  
2026-09-11 10:30:21 ppp[29886]: <6> 261090 ppp send IPCP Req  
options(addr=100.82.202.84;dns1=0.0.0.0;dns2=0.0.0.0;)  
2026-09-11 10:30:18 upnp[528]: <6> 217504 Service start  
2026-09-11 10:30:18 upnp[528]: <6> 217505 Service stop  
2026-09-11 10:30:17 remote-management[32689]: <6> 282505 Service stop  
2026-09-11 10:30:15 nat[32117]: <6> 211501 Initialization succeeded  
2026-09-11 10:30:15 nat[32117]: <6> 211501 Initialization succeeded  
2026-09-11 10:30:14 ppp[29886]: <6> 261091 ppp receive IPCP ACK  
2026-09-11 10:30:14 ppp[29886]: <6> 261101 ppp receive IPV6CP ACK  
2026-09-11 10:30:14 ppp[29886]: <6> 261090 ppp send IPCP Req  
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)  
2026-09-11 10:30:14 ppp[29886]: <6> 261100 ppp send IPV6CP Req  
options(ifaceid=cde8:c5f0:a11:acf2 ;)  
2026-09-11 10:30:11 ppp[29886]: <6> 261090 ppp send IPCP Req  
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)  
2026-09-11 10:30:11 ppp[29886]: <6> 261093 ppp receive IPCP NAK  
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)  
2026-09-11 10:30:11 ppp[29886]: <6> 261100 ppp send IPV6CP Req  
options(ifaceid=cde8:c5f0:a11:acf2 ;)
```

2026-09-11 10:30:11 ppp[29886]: <6> 261090 ppp send IPCP Req
options(addr=0.0.0.0;dns1=0.0.0.0;dns2=0.0.0.0;)
2026-09-11 10:30:11 ppp[29886]: <6> 261081 ppp receive CHAP Success: <null>
2026-09-11 10:30:10 ppp[29886]: <6> 261078 ppp send CHAP Response
name=0701442656@qld.exetel.com.au
2026-09-11 10:30:10 ppp[29886]: <6> 261077 ppp receive CHAP Challenge name=bdr03-
sat-454stpau-bne.au
2026-09-11 10:30:10 ppp[29886]: <6> 261064 ppp receive LCP ACK
2026-09-11 10:30:10 ppp[29886]: <6> 261060 ppp send LCP ACK
2026-09-11 10:30:10 ppp[29886]: <6> 261058 ppp receive LCP Request
options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x4c6cd47a;)
2026-09-11 10:30:10 ppp[29886]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0x793d7f7e;)
2026-09-11 10:30:10 ppp[29886]: <6> 261025 pppoe receive PADS sess-id(40842)
2026-09-11 10:30:10 ppp[29886]: <6> 261024 pppoe send PADR Host-Uniq(74be)
2026-09-11 10:30:10 ppp[29886]: <6> 261022 pppoe receive PADO form AC-
MAC(ea:04:fe:e3:40:19)
2026-09-11 10:30:10 ppp[29886]: <6> 261023 pppoe receive PADO AC-Name(bdr03-
sat-454stpau-bne.au)
2026-09-11 10:30:10 ppp[29886]: <6> 261021 pppoe send PADI Host-Uniq(74be)
2026-09-11 10:30:10 ppp[29886]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:30:00 ppp[29886]: <6> 261021 pppoe send PADI Host-Uniq(74be)
2026-09-11 10:30:00 ppp[29886]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:55 ppp[29886]: <6> 261021 pppoe send PADI Host-Uniq(74be)
2026-09-11 10:29:55 ppp[29886]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:44 ppp[27657]: <6> 261021 pppoe send PADI Host-Uniq(6c09)
2026-09-11 10:29:44 ppp[27657]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:34 ppp[27657]: <6> 261021 pppoe send PADI Host-Uniq(6c09)
2026-09-11 10:29:34 ppp[27657]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:29 ppp[27657]: <6> 261021 pppoe send PADI Host-Uniq(6c09)
2026-09-11 10:29:29 ppp[27657]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:18 ppp[25167]: <6> 261021 pppoe send PADI Host-Uniq(624f)
2026-09-11 10:29:18 ppp[25167]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:08 ppp[25167]: <6> 261021 pppoe send PADI Host-Uniq(624f)
2026-09-11 10:29:08 ppp[25167]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:29:03 ppp[25167]: <6> 261021 pppoe send PADI Host-Uniq(624f)
2026-09-11 10:29:03 ppp[25167]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:51 ppp[22574]: <6> 261021 pppoe send PADI Host-Uniq(582e)
2026-09-11 10:28:51 ppp[22574]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:41 ppp[22574]: <6> 261021 pppoe send PADI Host-Uniq(582e)

2026-09-11 10:28:41 ppp[22574]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:36 ppp[22574]: <6> 261021 pppoe send PADI Host-Uniq(582e)
2026-09-11 10:28:36 ppp[22574]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:25 ppp[18738]: <6> 261021 pppoe send PADI Host-Uniq(4932)
2026-09-11 10:28:25 ppp[18738]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:15 ppp[18738]: <6> 261021 pppoe send PADI Host-Uniq(4932)
2026-09-11 10:28:15 ppp[18738]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:11 nat[18681]: <6> 211501 Initialization succeeded
2026-09-11 10:28:11 remote-management[19001]: <6> 282505 Service stop
2026-09-11 10:28:11 nat[18681]: <6> 211501 Initialization succeeded
2026-09-11 10:28:10 ppp[18738]: <6> 261021 pppoe send PADI Host-Uniq(4932)
2026-09-11 10:28:10 ppp[18738]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:28:02 ppp[13847]: <6> 261021 pppoe send PADI Host-Uniq(3617)
2026-09-11 10:28:02 ppp[13847]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:27:58 nat[16218]: <6> 211501 Initialization succeeded
2026-09-11 10:27:58 nat[16218]: <6> 211501 Initialization succeeded
2026-09-11 10:27:52 ppp[13847]: <6> 261021 pppoe send PADI Host-Uniq(3617)
2026-09-11 10:27:52 ppp[13847]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:27:50 nat[14290]: <6> 211501 Initialization succeeded
2026-09-11 10:27:50 remote-management[14579]: <6> 282505 Service stop
2026-09-11 10:27:50 nat[14290]: <6> 211501 Initialization succeeded
2026-09-11 10:27:47 ppp[13847]: <6> 261021 pppoe send PADI Host-Uniq(3617)
2026-09-11 10:27:47 ppp[13847]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-11 10:27:47 nat[13456]: <6> 211501 Initialization succeeded
2026-09-11 10:27:47 nat[13456]: <6> 211501 Initialization succeeded
2026-09-11 10:27:43 nat[12560]: <6> 211501 Initialization succeeded
2026-09-11 10:27:43 nat[12560]: <6> 211501 Initialization succeeded
2026-09-10 12:35:11 nat[16236]: <6> 211501 Initialization succeeded
2026-09-10 12:35:11 nat[16236]: <6> 211501 Initialization succeeded
2026-09-10 12:35:11 remote-management[16493]: <6> 282505 Service stop
2026-09-10 12:35:08 upnp[15230]: <6> 217504 Service start
2026-09-10 12:35:08 upnp[15230]: <6> 217505 Service stop
2026-09-10 12:35:05 remote-management[13851]: <6> 282505 Service stop
2026-09-10 12:35:03 nat[12480]: <6> 211501 Initialization succeeded
2026-09-10 12:35:03 nat[12480]: <6> 211501 Initialization succeeded
2026-09-10 12:35:02 ppp[9260]: <6> 261101 ppp receive IPV6CP ACK
2026-09-10 12:35:02 ppp[9260]: <6> 261091 ppp receive IPCP ACK
2026-09-10 12:35:02 ppp[9260]: <6> 261090 ppp send IPCP Req
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)

2026-09-10 12:35:02 ppp[9260]: <6> 261093 ppp receive IPCP NAK
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-09-10 12:35:02 ppp[9260]: <6> 261100 ppp send IPV6CP Req
options(ifaceid=342a:7b68:7c74:8f60 ;)
2026-09-10 12:35:02 ppp[9260]: <6> 261090 ppp send IPCP Req
options(addr=0.0.0.0;dns1=0.0.0.0;dns2=0.0.0.0;)
2026-09-10 12:35:02 ppp[9260]: <6> 261081 ppp receive CHAP Success: <null>
2026-09-10 12:35:01 ppp[9260]: <6> 261078 ppp send CHAP Response
name=0701442656@qld.exetel.com.au
2026-09-10 12:35:01 ppp[9260]: <6> 261077 ppp receive CHAP Challenge name=bdr03-
sat-454stpau-bne.au
2026-09-10 12:35:01 ppp[9260]: <6> 261060 ppp send LCP ACK
2026-09-10 12:35:01 ppp[9260]: <6> 261058 ppp receive LCP Request
options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x2846f35;)
2026-09-10 12:35:00 ppp[9260]: <6> 261064 ppp receive LCP ACK
2026-09-10 12:35:00 ppp[9260]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xa147f221;)
2026-09-10 12:34:57 ppp[9260]: <6> 261064 ppp receive LCP ACK
2026-09-10 12:34:57 ppp[9260]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xa147f221;)
2026-09-10 12:34:55 remote-management[10438]: <6> 282505 Service stop
2026-09-10 12:34:54 ppp[9260]: <6> 261064 ppp receive LCP ACK
2026-09-10 12:34:54 ppp[9260]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xa147f221;)
2026-09-10 12:34:54 nat[9859]: <6> 211501 Initialization succeeded
2026-09-10 12:34:54 nat[9859]: <6> 211501 Initialization succeeded
2026-09-10 12:34:51 ppp[9260]: <6> 261064 ppp receive LCP ACK
2026-09-10 12:34:51 ppp[9260]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xa147f221;)
2026-09-10 12:34:51 ppp[9260]: <6> 261025 pppoe receive PADS sess-id(33306)
2026-09-10 12:34:51 ppp[9260]: <6> 261024 pppoe send PADR Host-Uniq(242c)
2026-09-10 12:34:51 ppp[9260]: <6> 261022 pppoe receive PADO form AC-
MAC(ea:04:fe:e3:40:19)
2026-09-10 12:34:51 ppp[9260]: <6> 261023 pppoe receive PADO AC-Name(bdr03-
sat-454stpau-bne.au)
2026-09-10 12:34:51 ppp[9260]: <6> 261021 pppoe send PADI Host-Uniq(242c)
2026-09-10 12:34:51 ppp[9260]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 12:34:51 network[8440]: <6> 290003 Connect interface internet
2026-09-10 12:34:51 network[8440]: <6> 290003 Connect interface wan
2026-09-10 12:34:51 traffic-stats[10608]: <6> 269004 stats reset

2026-09-10 12:34:50 network[8440]: <6> 290005 Reload config
2026-09-10 12:34:50 nat[8592]: <6> 211501 Initialization succeeded
2026-09-10 12:34:50 nat[8592]: <6> 211501 Initialization succeeded
2026-09-10 12:34:49 ppp[14811]: <6> 261026 pppoe send PADT due to(phase disconnect device)
2026-09-10 12:34:49 ppp[14811]: <6> 261066 ppp send LCP TermReq due to User request
2026-09-10 12:34:49 network[8440]: <6> 290004 Disconnect interface wan
2026-09-10 12:34:48 network[8440]: <6> 290004 Disconnect interface wanv6
2026-09-10 12:34:47 network[8440]: <6> 290004 Disconnect interface internet
2026-09-10 12:34:47 network[8440]: <6> 290102 Set PPPoE, username is 0701442656@qld.exetel.com.au
2026-09-10 12:34:47 network[8440]: <6> 290100 Set WAN protocol to pppoe, operation is connect
2026-09-10 12:34:18 dhcps[5512]: <6> 212504 Service start
2026-09-10 10:46:35 nat[17410]: <6> 211501 Initialization succeeded
2026-09-10 10:46:35 nat[17410]: <6> 211501 Initialization succeeded
2026-09-10 10:46:32 upnp[16709]: <6> 217504 Service start
2026-09-10 10:46:32 upnp[16709]: <6> 217505 Service stop
2026-09-10 10:46:31 remote-management[16430]: <6> 282505 Service stop
2026-09-10 10:46:30 nat[15840]: <6> 211501 Initialization succeeded
2026-09-10 10:46:30 nat[15840]: <6> 211501 Initialization succeeded
2026-09-10 10:46:29 ppp[14811]: <6> 261101 ppp receive IPV6CP ACK
2026-09-10 10:46:29 ppp[14811]: <6> 261091 ppp receive IPCP ACK
2026-09-10 10:46:29 ppp[14811]: <6> 261090 ppp send IPCP Req options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-09-10 10:46:29 ppp[14811]: <6> 261093 ppp receive IPCP NAK options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-09-10 10:46:29 ppp[14811]: <6> 261100 ppp send IPV6CP Req options(ifaceid=0d9e:49d5:e1bd:972a ;)
2026-09-10 10:46:29 ppp[14811]: <6> 261090 ppp send IPCP Req options(addr=0.0.0.0;dns1=0.0.0.0;dns2=0.0.0.0;)
2026-09-10 10:46:29 ppp[14811]: <6> 261081 ppp receive CHAP Success: <null>
2026-09-10 10:46:28 ppp[14811]: <6> 261078 ppp send CHAP Response name=0701442656@qld.exetel.com.au
2026-09-10 10:46:28 ppp[14811]: <6> 261077 ppp receive CHAP Challenge name=bdr03-sat-454stpau-bne.au
2026-09-10 10:46:28 ppp[14811]: <6> 261060 ppp send LCP ACK
2026-09-10 10:46:28 ppp[14811]: <6> 261058 ppp receive LCP Request options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x1ed5b863;)
2026-09-10 10:46:28 ppp[14811]: <6> 261064 ppp receive LCP ACK

2026-09-10 10:46:28 ppp[14811]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xe167c1be;)
2026-09-10 10:46:25 ppp[14811]: <6> 261064 ppp receive LCP ACK
2026-09-10 10:46:25 ppp[14811]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xe167c1be;)
2026-09-10 10:46:22 ppp[14811]: <6> 261064 ppp receive LCP ACK
2026-09-10 10:46:22 ppp[14811]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xe167c1be;)
2026-09-10 10:46:19 ppp[14811]: <6> 261064 ppp receive LCP ACK
2026-09-10 10:46:19 ppp[14811]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xe167c1be;)
2026-09-10 10:46:18 ppp[14811]: <6> 261025 pppoe receive PADS sess-id(32653)
2026-09-10 10:46:18 ppp[14811]: <6> 261024 pppoe send PADR Host-Uniq(39db)
2026-09-10 10:46:18 ppp[14811]: <6> 261022 pppoe receive PADO form AC-
MAC(ea:04:fe:e3:40:19)
2026-09-10 10:46:18 ppp[14811]: <6> 261023 pppoe receive PADO AC-Name(bdr03-
sat-454stpau-bne.au)
2026-09-10 10:46:18 ppp[14811]: <6> 261021 pppoe send PADI Host-Uniq(39db)
2026-09-10 10:46:18 ppp[14811]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:46:07 ppp[12346]: <6> 261021 pppoe send PADI Host-Uniq(303a)
2026-09-10 10:46:07 ppp[12346]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:57 ppp[12346]: <6> 261021 pppoe send PADI Host-Uniq(303a)
2026-09-10 10:45:57 ppp[12346]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:52 ppp[12346]: <6> 261021 pppoe send PADI Host-Uniq(303a)
2026-09-10 10:45:52 ppp[12346]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:41 ppp[10625]: <6> 261021 pppoe send PADI Host-Uniq(2981)
2026-09-10 10:45:41 ppp[10625]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:31 ppp[10625]: <6> 261021 pppoe send PADI Host-Uniq(2981)
2026-09-10 10:45:31 ppp[10625]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:26 ppp[10625]: <6> 261021 pppoe send PADI Host-Uniq(2981)
2026-09-10 10:45:26 ppp[10625]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:15 ppp[6663]: <6> 261021 pppoe send PADI Host-Uniq(1a07)
2026-09-10 10:45:15 ppp[6663]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:05 ppp[6663]: <6> 261021 pppoe send PADI Host-Uniq(1a07)
2026-09-10 10:45:05 ppp[6663]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:45:01 nat[6618]: <6> 211501 Initialization succeeded
2026-09-10 10:45:00 remote-management[6925]: <6> 282505 Service stop
2026-09-10 10:45:00 nat[6618]: <6> 211501 Initialization succeeded
2026-09-10 10:45:00 ppp[6663]: <6> 261021 pppoe send PADI Host-Uniq(1a07)
2026-09-10 10:45:00 ppp[6663]: <6> 261026 pppoe send PADT due to(resending PADI)

2026-09-10 10:44:52 ppp[2655]: <6> 261021 pppoe send PADI Host-Uniq(a5f)
2026-09-10 10:44:52 ppp[2655]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:44:48 nat[5148]: <6> 211501 Initialization succeeded
2026-09-10 10:44:47 nat[5148]: <6> 211501 Initialization succeeded
2026-09-10 10:44:42 ppp[2655]: <6> 261021 pppoe send PADI Host-Uniq(a5f)
2026-09-10 10:44:42 ppp[2655]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:44:40 nat[3108]: <6> 211501 Initialization succeeded
2026-09-10 10:44:40 remote-management[3404]: <6> 282505 Service stop
2026-09-10 10:44:40 nat[3108]: <6> 211501 Initialization succeeded
2026-09-10 10:44:37 ppp[2655]: <6> 261021 pppoe send PADI Host-Uniq(a5f)
2026-09-10 10:44:37 ppp[2655]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-10 10:44:36 nat[2304]: <6> 211501 Initialization succeeded
2026-09-10 10:44:36 nat[2304]: <6> 211501 Initialization succeeded
2026-09-10 10:44:34 ppp[8049]: <6> 261026 pppoe send PADT due to(phase disconnect device)
2026-09-10 10:44:34 ppp[8049]: <6> 261066 ppp send LCP TermReq due to User request
2026-09-10 10:44:33 nat[1235]: <6> 211501 Initialization succeeded
2026-09-10 10:44:32 nat[1235]: <6> 211501 Initialization succeeded
2026-09-09 11:47:09 nat[14145]: <6> 211501 Initialization succeeded
2026-09-09 11:47:08 nat[14145]: <6> 211501 Initialization succeeded
2026-09-09 11:47:08 remote-management[15407]: <6> 282505 Service stop
2026-09-09 11:47:03 nat[12432]: <6> 211501 Initialization succeeded
2026-09-09 11:47:03 nat[12432]: <6> 211501 Initialization succeeded
2026-09-09 11:47:03 remote-management[13073]: <6> 282505 Service stop
2026-09-09 11:47:00 upnp[11250]: <6> 217504 Service start
2026-09-09 11:46:59 upnp[11250]: <6> 217505 Service stop
2026-09-09 11:46:58 remote-management[10569]: <6> 282505 Service stop
2026-09-09 11:46:56 nat[9682]: <6> 211501 Initialization succeeded
2026-09-09 11:46:56 nat[9682]: <6> 211501 Initialization succeeded
2026-09-09 11:46:53 imb[8498]: <6> 218507 Daemon connection succeeded
2026-09-09 11:46:53 imb[8498]: <6> 218012 ARP Binding disabled
2026-09-09 11:46:53 imb[8498]: <6> 218506 Config interface initialization succeeded
2026-09-09 11:46:53 imb[8498]: <6> 218501 Initialization succeeded
2026-09-09 11:46:49 ppp[8049]: <6> 261101 ppp receive IPV6CP ACK
2026-09-09 11:46:49 ppp[8049]: <6> 261091 ppp receive IPCP ACK
2026-09-09 11:46:49 ppp[8049]: <6> 261090 ppp send IPCP Req options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-09-09 11:46:49 ppp[8049]: <6> 261093 ppp receive IPCP NAK options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)

2026-09-09 11:46:49 ppp[8049]: <6> 261100 ppp send IPV6CP Req
options(ifaceid=699b:8424:e712:00fd ;)
2026-09-09 11:46:49 ppp[8049]: <6> 261090 ppp send IPCP Req
options(addr=0.0.0.0;dns1=0.0.0.0;dns2=0.0.0.0;)
2026-09-09 11:46:49 ppp[8049]: <6> 261081 ppp receive CHAP Success: <null>
2026-09-09 11:46:49 ppp[8049]: <6> 261078 ppp send CHAP Response
name=0701442656@qld.exetel.com.au
2026-09-09 11:46:49 ppp[8049]: <6> 261077 ppp receive CHAP Challenge name=bdr03-
sat-454stpau-bne.au
2026-09-09 11:46:49 ppp[8049]: <6> 261064 ppp receive LCP ACK
2026-09-09 11:46:49 ppp[8049]: <6> 261060 ppp send LCP ACK
2026-09-09 11:46:49 ppp[8049]: <6> 261058 ppp receive LCP Request
options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x2038948;)
2026-09-09 11:46:49 ppp[8049]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd805b1d4;)
2026-09-09 11:46:49 ppp[8049]: <6> 261025 pppoe receive PADS sess-id(24377)
2026-09-09 11:46:48 ppp[8049]: <6> 261024 pppoe send PADR Host-Uniq(1f71)
2026-09-09 11:46:48 ppp[8049]: <6> 261022 pppoe receive PADO form AC-
MAC(ea:04:fe:e3:40:19)
2026-09-09 11:46:48 ppp[8049]: <6> 261023 pppoe receive PADO AC-Name(bdr03-
sat-454stpau-bne.au)
2026-09-09 11:46:48 ppp[8049]: <6> 261021 pppoe send PADI Host-Uniq(1f71)
2026-09-09 11:46:48 ppp[8049]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 11:46:46 upnp[7471]: <6> 217504 Service start
2026-09-09 11:46:45 upnp[7471]: <6> 217505 Service stop
2026-09-09 11:46:45 nat[5656]: <6> 211501 Initialization succeeded
2026-09-09 11:46:45 remote-management[6976]: <6> 282505 Service stop
2026-09-09 11:46:45 nat[5656]: <6> 211501 Initialization succeeded
2026-09-09 11:46:43 traffic-stats[10608]: <6> 269004 stats reset
2026-09-09 11:46:41 nat[4741]: <6> 211501 Initialization succeeded
2026-09-09 11:46:41 traffic-stats[10608]: <6> 269002 stats on
2026-09-09 11:46:41 traffic-stats[10608]: <6> 269003 stats off
2026-09-09 11:46:41 nat[4741]: <6> 211501 Initialization succeeded
2026-09-09 11:46:39 ppp[4754]: <6> 261026 pppoe send PADT due to(phase disconnect
device)
2026-09-09 11:46:39 ppp[4754]: <6> 261066 ppp send LCP TermReq due to User request
2026-09-09 11:46:37 network[4397]: <5> 290250 Restart interfaces
2026-09-09 11:46:37 network[4397]: <6> 290106 Set MAC address to 7A:F4:E5:3F:42:6C
2026-09-09 11:46:37 network[4397]: <6> 290150 Set mac clone
2026-09-09 10:47:42 nat[6789]: <6> 211501 Initialization succeeded

2026-09-09 10:47:42 nat[6789]: <6> 211501 Initialization succeeded
2026-09-09 10:47:38 upnp[5719]: <6> 217504 Service start
2026-09-09 10:47:38 upnp[5719]: <6> 217505 Service stop
2026-09-09 10:47:37 remote-management[5407]: <6> 282505 Service stop
2026-09-09 10:47:37 nat[4820]: <6> 211501 Initialization succeeded
2026-09-09 10:47:36 nat[4820]: <6> 211501 Initialization succeeded
2026-09-09 10:47:36 ppp[4754]: <6> 261101 ppp receive IPV6CP ACK
2026-09-09 10:47:35 ppp[4754]: <6> 261091 ppp receive IPCP ACK
2026-09-09 10:47:35 ppp[4754]: <6> 261090 ppp send IPCP Req
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-09-09 10:47:35 ppp[4754]: <6> 261093 ppp receive IPCP NAK
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-09-09 10:47:35 ppp[4754]: <6> 261100 ppp send IPV6CP Req
options(ifaceid=d82a:9be5:2adf:ccf4 ;)
2026-09-09 10:47:35 ppp[4754]: <6> 261090 ppp send IPCP Req
options(addr=0.0.0.0;dns1=0.0.0.0;dns2=0.0.0.0;)
2026-09-09 10:47:35 ppp[4754]: <6> 261081 ppp receive CHAP Success: <null>
2026-09-09 10:47:35 ppp[4754]: <6> 261078 ppp send CHAP Response
name=0701442656@qld.exetel.com.au
2026-09-09 10:47:35 ppp[4754]: <6> 261077 ppp receive CHAP Challenge name=bdr03-
sat-454stpau-bne.au
2026-09-09 10:47:35 ppp[4754]: <6> 261064 ppp receive LCP ACK
2026-09-09 10:47:35 ppp[4754]: <6> 261060 ppp send LCP ACK
2026-09-09 10:47:35 ppp[4754]: <6> 261058 ppp receive LCP Request
options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x2dc68e5e;)
2026-09-09 10:47:35 ppp[4754]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xe496859f;)
2026-09-09 10:47:34 ppp[4754]: <6> 261025 pppoe receive PADS sess-id(24016)
2026-09-09 10:47:34 ppp[4754]: <6> 261024 pppoe send PADR Host-Uniq(1292)
2026-09-09 10:47:34 ppp[4754]: <6> 261022 pppoe receive PADO form AC-
MAC(ea:04:fe:e3:40:19)
2026-09-09 10:47:34 ppp[4754]: <6> 261023 pppoe receive PADO AC-Name(bdr03-
sat-454stpau-bne.au)
2026-09-09 10:47:34 ppp[4754]: <6> 261021 pppoe send PADI Host-Uniq(1292)
2026-09-09 10:47:34 ppp[4754]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:47:33 ppp[3031]: <6> 261027 pppoe receive PADT
2026-09-09 10:47:33 ppp[3031]: <6> 261067 ppp receive LCP TermReq
2026-09-09 10:47:33 ppp[3031]: <6> 261064 ppp receive LCP ACK
2026-09-09 10:47:33 ppp[3031]: <6> 261060 ppp send LCP ACK

2026-09-09 10:47:33 ppp[3031]: <6> 261058 ppp receive LCP Request
options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x7e2764fb;)
2026-09-09 10:47:33 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:30 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:27 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:24 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:21 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:18 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:15 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:12 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:09 ppp[3031]: <6> 261060 ppp send LCP ACK
2026-09-09 10:47:09 ppp[3031]: <6> 261058 ppp receive LCP Request
options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x11b58f1;)
2026-09-09 10:47:09 ppp[3031]: <6> 261061 ppp send LCP Request
options(mru=1480;magic=0xd3b8a4a8;)
2026-09-09 10:47:09 ppp[3031]: <6> 261025 pppoe receive PADS sess-id(24012)
2026-09-09 10:47:09 ppp[3031]: <6> 261024 pppoe send PADR Host-Uniq(bd7)
2026-09-09 10:47:09 ppp[3031]: <6> 261022 pppoe receive PADO form AC-
MAC(ea:04:fe:e3:40:19)
2026-09-09 10:47:09 ppp[3031]: <6> 261023 pppoe receive PADO AC-Name(bdr03-
sat-454stpau-bne.au)
2026-09-09 10:47:09 ppp[3031]: <6> 261021 pppoe send PADI Host-Uniq(bd7)
2026-09-09 10:47:09 ppp[3031]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:58 ppp[32517]: <6> 261021 pppoe send PADI Host-Uniq(7f05)
2026-09-09 10:46:58 ppp[32517]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:48 ppp[32517]: <6> 261021 pppoe send PADI Host-Uniq(7f05)
2026-09-09 10:46:48 ppp[32517]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:43 ppp[32517]: <6> 261021 pppoe send PADI Host-Uniq(7f05)
2026-09-09 10:46:43 ppp[32517]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:31 ppp[30848]: <6> 261021 pppoe send PADI Host-Uniq(7880)
2026-09-09 10:46:31 ppp[30848]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:21 ppp[30848]: <6> 261021 pppoe send PADI Host-Uniq(7880)

2026-09-09 10:46:21 ppp[30848]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:16 ppp[30848]: <6> 261021 pppoe send PADI Host-Uniq(7880)
2026-09-09 10:46:16 ppp[30848]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:46:05 ppp[28087]: <6> 261021 pppoe send PADI Host-Uniq(6db7)
2026-09-09 10:46:05 ppp[28087]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:55 ppp[28087]: <6> 261021 pppoe send PADI Host-Uniq(6db7)
2026-09-09 10:45:55 ppp[28087]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:50 ppp[28087]: <6> 261021 pppoe send PADI Host-Uniq(6db7)
2026-09-09 10:45:50 ppp[28087]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:39 ppp[25059]: <6> 261021 pppoe send PADI Host-Uniq(61e3)
2026-09-09 10:45:39 ppp[25059]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:29 ppp[25059]: <6> 261021 pppoe send PADI Host-Uniq(61e3)
2026-09-09 10:45:29 ppp[25059]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:25 nat[25015]: <6> 211501 Initialization succeeded
2026-09-09 10:45:25 remote-management[25320]: <6> 282505 Service stop
2026-09-09 10:45:24 nat[25015]: <6> 211501 Initialization succeeded
2026-09-09 10:45:24 ppp[25059]: <6> 261021 pppoe send PADI Host-Uniq(61e3)
2026-09-09 10:45:24 ppp[25059]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:16 ppp[20309]: <6> 261021 pppoe send PADI Host-Uniq(4f55)
2026-09-09 10:45:16 ppp[20309]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:12 nat[23538]: <6> 211501 Initialization succeeded
2026-09-09 10:45:12 nat[23538]: <6> 211501 Initialization succeeded
2026-09-09 10:45:06 ppp[20309]: <6> 261021 pppoe send PADI Host-Uniq(4f55)
2026-09-09 10:45:06 ppp[20309]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:04 nat[21601]: <6> 211501 Initialization succeeded
2026-09-09 10:45:04 remote-management[21918]: <6> 282505 Service stop
2026-09-09 10:45:04 nat[21601]: <6> 211501 Initialization succeeded
2026-09-09 10:45:01 ppp[20309]: <6> 261021 pppoe send PADI Host-Uniq(4f55)
2026-09-09 10:45:01 ppp[20309]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-09-09 10:45:01 nat[19985]: <6> 211501 Initialization succeeded
2026-09-09 10:45:01 nat[19985]: <6> 211501 Initialization succeeded
2026-09-09 10:44:58 ppp[13532]: <6> 261026 pppoe send PADT due to(phase disconnect device)
2026-09-09 10:44:58 ppp[13532]: <6> 261066 ppp send LCP TermReq due to User request
2026-09-09 10:44:57 nat[18673]: <6> 211501 Initialization succeeded
2026-09-09 10:44:57 nat[18673]: <6> 211501 Initialization succeeded
2026-09-09 04:02:31 remote-management[23037]: <6> 282505 Service stop
2026-09-09 04:02:30 nat[21809]: <6> 211501 Initialization succeeded
2026-09-09 04:02:30 nat[21809]: <6> 211501 Initialization succeeded

2026-09-09 04:02:27 nat[20508]: <6> 211501 Initialization succeeded
2026-09-09 04:02:27 nat[20508]: <6> 211501 Initialization succeeded
2026-09-09 04:02:27 remote-management[20765]: <6> 282505 Service stop
2026-09-09 04:02:22 upnp[18871]: <6> 217504 Service start
2026-09-09 04:02:22 upnp[18871]: <6> 217505 Service stop
2026-09-09 04:02:21 remote-management[18533]: <6> 282505 Service stop
2026-09-09 04:02:19 nat[17970]: <6> 211501 Initialization succeeded
2026-09-09 04:02:19 nat[17970]: <6> 211501 Initialization succeeded
2026-09-09 04:02:15 imb[16872]: <6> 218507 Daemon connection succeeded
2026-09-09 04:02:15 imb[16872]: <6> 218012 ARP Binding disabled
2026-09-09 04:02:15 imb[16872]: <6> 218506 Config interface initialization succeeded
2026-09-09 04:02:15 imb[16872]: <6> 218501 Initialization succeeded
2026-09-09 04:02:14 nat[5666]: <6> 211021 IPSEC ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 L2TP ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 PPTP ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 SIP ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 RTSP ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 H323 ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 TFTP ALG enabled
2026-09-09 04:02:14 nat[5666]: <6> 211021 FTP ALG enabled
2026-09-09 04:02:14 upnp[16311]: <6> 217504 Service start
2026-09-09 04:02:13 upnp[16311]: <6> 217505 Service stop
2026-09-09 04:02:13 nat[5666]: <6> 211501 Initialization succeeded
2026-09-09 04:02:12 nat[5666]: <6> 211501 Initialization succeeded
2026-09-09 04:02:12 remote-management[15808]: <6> 282505 Service stop
2026-05-19 00:00:59 led-controller[1945]: <6> 288051 Start to run STATUS_ON
2026-05-19 00:00:58 ppp[13532]: <6> 261101 ppp receive IPV6CP ACK
2026-05-19 00:00:58 ppp[13532]: <6> 261091 ppp receive IPCP ACK
2026-05-19 00:00:58 ppp[13532]: <6> 261090 ppp send IPCP Req
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-05-19 00:00:58 ppp[13532]: <6> 261093 ppp receive IPCP NAK
options(addr=100.82.202.84;dns1=119.40.106.35;dns2=119.40.106.36;)
2026-05-19 00:00:58 ppp[13532]: <6> 261100 ppp send IPV6CP Req
options(ifaceid=bc3b:a272:641b:52e6 ;)
2026-05-19 00:00:58 ppp[13532]: <6> 261090 ppp send IPCP Req
options(addr=0.0.0.0;dns1=0.0.0.0;dns2=0.0.0.0;)
2026-05-19 00:00:58 ppp[13532]: <6> 261081 ppp receive CHAP Success: <null>
2026-05-19 00:00:57 ppp[13532]: <6> 261078 ppp send CHAP Response
name=0701442656@qld.exetel.com.au

2026-05-19 00:00:57 ppp[13532]: <6> 261077 ppp receive CHAP Challenge name=bdr03-sat-454stpau-bne.au
2026-05-19 00:00:57 ppp[13532]: <6> 261064 ppp receive LCP ACK
2026-05-19 00:00:57 ppp[13532]: <6> 261060 ppp send LCP ACK
2026-05-19 00:00:57 ppp[13532]: <6> 261058 ppp receive LCP Request options(mru=1492;authtype=PPP_CHAP|type(MD5);magic=0x3646fb6c;)
2026-05-19 00:00:57 ppp[13532]: <6> 261061 ppp send LCP Request options(mru=1480;magic=0xc7d6f4c9;)
2026-05-19 00:00:57 ppp[13532]: <6> 261025 pppoe receive PADS sess-id(21565)
2026-05-19 00:00:57 ppp[13532]: <6> 261024 pppoe send PADR Host-Uniq(34dc)
2026-05-19 00:00:57 ppp[13532]: <6> 261022 pppoe receive PADO form AC-MAC(ea:04:fe:e3:40:19)
2026-05-19 00:00:57 ppp[13532]: <6> 261023 pppoe receive PADO AC-Name(bdr03-sat-454stpau-bne.au)
2026-05-19 00:00:57 ppp[13532]: <6> 261021 pppoe send PADI Host-Uniq(34dc)
2026-05-19 00:00:57 ppp[13532]: <6> 261026 pppoe send PADT due to(resending PADI)
2026-05-19 00:00:56 qos[12848]: <6> 259504 Service start
2026-05-19 00:00:55 qos[12848]: <6> 259502 Function enabled
2026-05-19 00:00:54 led-controller[1945]: <6> 288051 Start to run GENERAL
2026-05-19 00:00:47 traffic-stats[10600]: <6> 269504 Service start
2026-05-19 00:00:47 imb[10422]: <6> 218507 Daemon connection succeeded
2026-05-19 00:00:47 imb[10422]: <6> 218012 ARP Binding disabled
2026-05-19 00:00:47 imb[10422]: <6> 218506 Config interface initialization succeeded
2026-05-19 00:00:47 imb[10422]: <6> 218501 Initialization succeeded
2026-05-19 00:00:44 factory-reset[9663]: <6> 284504 Service start
2026-05-19 00:00:42 parental-control[8826]: <6> 229504 Service start
2026-05-19 00:00:42 parental-control[8826]: <6> 229502 Function enabled
2026-05-19 00:00:41 access-control[5544]: <6> 239504 Service start
2026-05-19 00:00:41 access-control[5544]: <6> 239503 Function disabled
2026-05-19 00:00:10 nat[5014]: <7> 211001 Flush conntrack
2026-05-19 00:00:10 nat[5014]: <6> 211502 Function enabled
2026-05-19 00:00:10 nat[5014]: <5> 211051 Create NAT chain succeeded
2026-05-19 00:00:10 nat[5014]: <6> 211501 Initialization succeeded
2026-05-19 00:00:09 nat[5014]: <6> 211501 Initialization succeeded
2026-05-19 00:00:07 basic-security[3956]: <6> 219504 Service start
2026-05-19 00:00:07 basic-security[3956]: <5> 219606 Flush conntrack table succeeded
2026-05-19 00:00:07 firewall[2677]: <6> 209504 Service start
2026-05-19 00:00:00 time-settings[2020]: <6> 279504 Service start
1970-01-01 00:00:19 led-controller[1945]: <6> 288051 Start to run STATUS_SAN
1970-01-01 00:00:18 led-controller[1945]: <6> 288504 Service start

